

# What is an Industrial Revolution?

A monumental transition in manufacturing that is enabled by the emergence of a new technology.

The fourth industrial revolution: Leveraging advancements in cloud computing and machine to systems integration, 4.0 reprioritizes human involvement towards value-add activities.

## The Principal:

#### Flow

- Waste free manufacturing through perfect transfer of people, materials and information
- Outcomes are predictable, cost-effective, profitable

#### The Problem:


#### Variation

- What interrupts flow?
  - Procedure variations
  - ► Equipment variations
  - Material variations
  - Natural variations

Every revolution achieves the same goal: increase flow, limit variation





### U.S. Manufacturing GDP Share vs. Employment Share



- Manufacturing share of real GDP has been constant for the past 50 years
- Employment share has dropped significantly
- Indicates ever-increasing efficiency

#### The Four Revolutions









1.0 (1760-1870)

- Steam power
- Mechanization

2.0 (1870-1920)

- Electric power
- Mass-Production


3.0 (1970-2000)

- Computing
- Automation

4.0 (2000-present)

- Cloud computing
- Complex automation

## Industry 4.0 Technologies



## Industrial Internet of Things (IIoT)

- The internet of things is the concept of connecting any device to the internet and other connected devices. IIoT represents the industrial application of Internet of Things
- In practice, IoT is hardware that uses wireless communication to automatically communicate real-time signals to a cloud database
- Manufacturers use IIoT to learn about the cohesive performance of their operations and predict future variances




### Usages of Production Data











Date

1/1/2019 9/28/2019 Customer

ΑII

Assigned Employee

Workcenter

Miller, Dan Martin, Tim

ΑII

Part ID

Material Variance
Direct Labor Variance
Overhead Variance

All

Variances by Customer

(\$10K)

(\$20K)

(\$30K)



To Shop

75.63%

(\$44,059.27)

Total Labor Variance

(\$43,608)

Total Material Variance


(\$14,414.74)


Total Overhead Variance

267,668

Total Units Produced














# Flipping the Script












# Key Takeaway

Visibility Insights Decisions Automation

### Typical Return on Investment Focus Areas

- 1) Improving machine in-cycle time
- 2) Reducing labor variances
- 3) Reducing material variances
- 4) Reducing turnover by improving engagement

- 5) Elimination of data recording and data entry activities
- 6) Elimination of report gathering activities
- 7) Improving inventory turnover



## Wipfli Case Study

#### Metals Contract Manufacturer

#### Value statements

- \$100M → \$200M company with no additional resources
- Develop managerial habits of statistical analysis
- Create a culture of continuous improvement

#### **Anticipated Return on Investment**

- 40 machines, increase average in-cycle time from 45% to 60%
- Improve manufacturing standard attainment from 85% to 95%
- Approximate \$5.2M of Annual Benefit



## Wipfli Case Study

#### Plastic Extrusion Manufacturer

#### Value statements

- What/when/where should we produce product?
- Should we use virgin or recycled material?
- What is our optimal shift staffing pattern?
- Develop managerial habits of statistical analysis

#### **Anticipated Return on Investment**

- 35 lines, increase average in-cycle time from 60% to 70%
- Reduce inventory carrying costs by 20%
- Approximate \$8-10M of Annual Benefit



### 5 Common Pitfalls of Scaling Digital Transformation

McKinsey & Company: Capturing the true value of Industry 4.0 (April 13, 2022)

- Siloed implementation independent delivery teams decoupled from the business
- 2. Failure to adapt deploying one-size-fits-all approach
- 3. Analysis paralysis getting stuck early
- 4. Technology-driven, not Value-driven decoupled from purpose/value
- 5. Perfect is the enemy of good waiting until everything's low cost and low risk

<u>Takeaway:</u> work together around common goals and be flexible with the execution

# Questions?